

TOP SECRET**PRIORITY**

OUT57194

TOP SECRET 172132Z

PRIORITY CITE 5930ATTN:

SUBJ: EVALUATION OF MISSION S025A

1. CAMERA NUMBER 119 WAS USED IN MISSION S025A FLOWN ON 7 NOVEMBER 1965. PROCESSING WAS ACCOMPLISHED BY EASTMAN KODAK.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9L SIDE: THERE ARE HEAT SPLICES BETWEEN TITLED FRAMES 128/129, 749/750 AND 1542/1543. A SERIES OF MINUS DENSITY DOTS ARE PRESENT 0.75" FROM THE OUTBOARD EDGE IN THE FIRST 5 FRAMES. THERE IS A MANUFACTURING SPLICE IN FRAME 1619.

C. 9R SIDE: MINOR TRACES OF EDGE FOG CAN BE DETECTED ALONG THE OUTBOARD EDGE. THERE ARE HEAT SPLICES BETWEEN TITLED FRAMES 810/811, 1691/1692 AND 1712/1713. THERE IS A CREASE IN FRAME 1692.

D. BOTH SIDES: ROLLER CHATTER IS PRESENT ALONG THE INBOARD EDGE THROUGHOUT THE ENTIRE MISSION.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING ANOMALIES NOTED ON THIS MISSION. THE TITLED FRAMES ARE NUMBER 5 THROUGH 2424.

3. POSITIVE:

A. THE PI SUITABILITY WAS GOOD WHERE NOT DEGRADED BY HAZE AND CLOUDS.

1965 NOV 17 21 42Z

18 NOV 1965

25X1

DISTRIBUTION		
Cy No.	Office	Action
✓	File	25X1
	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4,5	TID	✓
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy
Sanitized

TOP SECRET

-2-

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURE APPROXIMATELY 15 PERCENT OF THE PHOTO-
GRAPHY.

D. NO MATERIAL WAS EDITED FROM THIS MISSION.

T O P S E C R E T

--END OF MESSAGE--

1